

Hilti Tool Service – Drill and Drive

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)
Cordless Drill / Drive	SF 2-A	2016/01 –	1	N/A		N/A
	SFD 2-A	2016/01 –	1	N/A		N/A
	SF 14-A	2011/05 –	2	423.00		
	SFC 14-A	2011/04 –	2	320.00		
	SFH 14-A	2009/04 –	2	494.00		
	SF 22-A	2009/04 –	2	479.00		
	SF 6-A22	2017/01 –	2	574.00		
	SFC 22-A	2011/04 –	2	325.00		
	SFH 22-A	2009/04 –	2	544.00		
	SF 6H-A22		2	557.00		
	ST 1800-A22	2011/09 –	2	883.00		
Cordless Impact Drive	SID 2-A	2013/01 –	1	N/A		N/A
	SID 14-A	2011/06 –	2	532.00		
	SID 22-A	2012/01 –	2	335.00		
	SID 4-A22	2017/03 –	2	479.00		
Cordless Impact Wrench	SIW 14-A	2011/06 –	2	586.00		
	SIW 22-A	2012/01 –	2	573.00		
	SIW 22T-A	2010/09 –	2	712.00		
Corded Driver	ST 1800	2003/05 –	1	900.00		

Hilti Tool Service – Breaker

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾	Successor Product	Repair service until (DD.MM.YYYY)
Breaker	TE 500-X	2008/01 –	1	780.00		
	TE 800-AVR	2015/02 –	2	1,850.00		
	TE 1000-AVR	09/05 – 15/12	2	2,450.00		31.12.2030
	TE 1000_AVR new	2014/06 –	2	2,450.00		
	TE 1500	2009/11 –	2	3,008.00	TE 2000	
	TE 2000-AVR		2	2,905.00		

1) Valid until 31.12.2020. All prices subject to change.

"N/A" indicates non-reparable items which are not covered by Hilti Tool Services and warranty.

2) Unless otherwise specified, parts of drilling and driving tools are kept normally for 7 years for repair services (15 years for breaker) or Hilti will provide trade-in offer if parts are unavailable.

Hilti Tool Service – Drilling and Chiseling

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)
Corded Rotary Hammer	TE 2	2007/03 –	2	350.00		
	TE 2-M_02	2007/03 –	2	609.00		
	TE 2-S_02	2007/03 –	2	517.00		
	TE 6-S	02/08 – 11/12	2	690.00		31.12.2026
	TE 7	2010/11 –	2	600.00		
	TE 7-C	2006/04 –	2	854.00		
	TE 15-C	98/05 – 04/12	2	N/A		31.12.2019
	TE 16	04/04 – 10/12	2	N/A	TE 30	31.07.2017
	TE 16-C	04/04 – 10/12	2	N/A	TE 30-C-AVR	31.07.2017
	TE 25	97/01 – 07/12	2	N/A	TE 30 G2	31.07.2017
Corded Combi Hammer	TE 30 G2	2017/06 –	2	1,170.00		
	TE 30-C-AVR	2009/05 –	2	1,405.00		
	TE 40	2007/04 –	2	1,926.00	TE 30 G2	
	TE 50 AVR	2007/02 –	2	1,471.00		
	TE 55	96/05 – 04/12	2	N/A	TE 60	31.07.2017
	TE 56	03/03 – 09/09	2	N/A	TE 60	31.07.2017
	TE 60	2008/09 –	2	2,017.00		
	TE 60-ATC	2011/06 –	2	3,049.00		
	TE 70	2007/09 –	2	4,315.00		
	TE 70-ATC	07/09 – 14/12	2	3,831.00		31.12.2019
	TE 70-ATC-AVR	2013/01 –	2	5,050.00		
	TE 70-AVR		2	3,800		
	TE 76-ATC	00/01 – 08/12	2	N/A	TE 70-ATC	31.07.2017
Cordless Rotary Hammer	TE 2-A	04/01 – 13/12	2	550.00		31.12.2020
	TE 2-A22	2012/02 –	2	550.00		
	TE 4-A22	2010/05 –	2	596.00		
	TE 6-A_01	99/06 – 10/12	2	N/A	TE 6-A36-AVR	31.07.2017
	TE 6-A_02	06/04 – 10/12	2	N/A	TE 6-A36-AVR	31.07.2017
	TE 6-A36-AVR	2010/04 –	2	1023.00		
	TE 7-A	06/09 – 14/12	2	1,370.00		31.12.2029
	TE 30-A36	2013/01 –	2	2,150.00		
	TE 60-A36		2	3,482.00		

1) Valid until 31.12.2020. All prices subject to change.

"N/A" indicates non-reparable items which are not covered by Hilti Tool Services and warranty.

2) Unless otherwise specified, parts of rotary hammers are kept normally for 15 years for repair services or Hilti will provide trade-in offer if parts are unavailable.

Hilti Tool Service – Cutting, Grinding & Sawing

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)
Angle Grinders	AG 100-7S	2014/05 –	N/A	N/A		N/A
	AG 100-8S	2014/05 –	N/A	N/A		N/A
	AG 180-20D	2014/05 –	1 ⁴⁾	523.00		
	DAG 100-S	09/01 – 14/12	1	247.00		31.12.2021
	DAG 125-S	06/09 – 16/12	1	519.00	AG 125 15-DB	31.12.2023
	DCG 125-S	06/09 – 17/12	1	597.00	AG 125 15-DB	31.12.2024
	AG 125 15-DB	2017/01 –	1	900.00		
	AG125 A-22	2012/02 –	1	725.00		
	AG125 A-36	2016/01 –	1	725.00		
Reciprocation Saws	WSR 22-A	2009/09 –	2	800.00	SR 4-A22	
	SR 4-A22		2	791.00		
	SR 6-A22		2	1,009.00		
	WSR-36A	2008/01 –	2	1,248.00	SR 30-A36	
	SR 30-A36		2	1,170.00		
	WSR 900-PE	2003/07 –	2	842.00		
Jig Saws	WSJ 750-ET	03/09 – 16/12	2	1,074.00		31.12.2023
	WSJ 850-ET	03/09 – 16/12	2	1,068.00		31.12.2023
Circular Saws	SCM 22-A	2012/03 –	2	780.00		
	SCW 22-A	2011/04 –	2	862.00		
	SC 70W-A22	2015/06 –	2	990.00		
Band Saws	SB 4-A22		2	678.00		

Hilti Tool Service – Diamond Coring & Sawing

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)
Diamond Coring	DD 30-W	2017/05 –	2	4,902.00		
	DD REC-1	2000/04 –	2	3,975.00		
	DD VP-U	2010/01 –	2	2,000.00		
	DD120	2007/07 –	2	2,700.00		
	DD160	2012/01 –	2	3,981.00		
	DD 200	2014/03 –	2	4,800.00		
	DD 350	2015/03 –	2 ²⁾	15,968.00		
	DD 500	2015/03 –	2 ²⁾	17,500.00		
Track Sawing	DS TS20-E	2010/09 –	1 ²⁾	79,580.00		
	DST 20-CA		1 ²⁾	28,000.00		
Wire Sawing	DS WS 15	2008/10 –	1	83,326.43		

1) Valid until 31.12.2020. All prices subject to change. "N/A" indicates non-reparable items which are not covered by Hilti Tool Services and warranty.

2) No-cost warranty for heavy diamond tools (DD350 & DD500) with operating hour counter : 2 years or 200 hours (whichever is reached first)

3) Unless otherwise specified, parts of angle grinders and saws are kept normally for 7 years for repair services (15 years for diamond tool) or Hilti will provide trade-in offer if parts are unavailable.

4) AG180-20D comes with 2 times free repair service in the first year of purchase.



Hilti Tool Service – Measuring Systems

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)	Calibration fee ²⁾ (HKD)
Laser Range Meters	PD 4	07/09 – 13/12	1	N/A	PD S	N/A	2,160.00
	PD 5	2011/07 –	1	N/A	PD S	N/A	2,160.00
	PD40	07/04 – 14/12	2	N/A	PD-E	31.12.2019	2,160.00
	PD42	07/04 – 14/12	2	N/A	PD-E	31.12.2019	2,160.00
	PD-I	2014/01 –	2	N/A	PD-E		2,160.00
	PD-E	2014/01 –	2	N/A			2,160.00
Multi-Directional Lasers	PML 42	10/12 – 15/12	2	N/A	PM 2-L	31.12.2020	2,160.00
	PMC 46	2010/01 –	2	2,662.00			2,160.00
	PM 2-L	2012/12 –	2	727.00			2,160.00
	PM4-M	2012/12 –	2 ³⁾	1,263.00			2,160.00
Rotating Lasers	PRI 2	07/02 – 15/12	2	4,846.00		31.12.2020	2,570.00
	PRE 3	09/03 – 13/12	2	N/A	PR 2-HS	31.12.2018	2,570.00
	PR 3	2012/01 –	2	5,080.00			2,570.00
	PR2-HS	2013/07 –	2	4,736.00			2,570.00
Detection Systems	PS 30	2010/01 –	2	900.00	PS 50		2,060.00
	PS 35	10/01 – 15/12	2	1,720.00	PS 50	31.12.2020	2,060.00
	PS 38	10/07 – 15/12	2	2,321.00	PS 50	31.12.2020	2,060.00
	PS 50	2014/09 –	2	2,948.00			2,060.00
	PS 200	2004/11 –	2	35,000.00			5,810.00
	PS 250	2013/01 –	2	57,687.00			5,810.00
	PS 1000	2012/01 –	2	78,618.00			5,810.00

Hilti Tool Service – Vacuum Cleaner

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)
Vacuum cleaner	VC 20-U(M)	2008/04 –	2	2,042.00		
	VC 40-U(M)	2008/01 –	2	2,043.00		
	VC 40-U(M)-Y	2013/01 –	2	6,518.00		

- 1) Valid until 31.12.2020. All prices subject to change. "N/A" indicates non-reparable items which are not covered by Hilti Tool Services and warranty.
- 2) The charge for calibration service is not covered by Hilti Tool Service warranty. Test Result values are included in the Calibration Fee.
- 3) No Cost Period is excluded for PM 4-M since purchased from 2019
- 3) Unless otherwise specified, parts of measuring tools are kept normally for 5-7 years for repair services (7 year for vacuum cleaner) or Hilti will provide trade-in offer if parts are unavailable.



Hilti Tool Service – Direct Fastening

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	²⁾ Repair service until (DD.MM.YYYY)
Power-actuated (DX)	DX 36	90/06 –16/12	2	2,356.00	DX 2	31.12.2031
	DX 2	2014/09 –	1	1,244.00		
	DX 36-M	90/06 –07/12	2	1,770.00		31.12.2022
	DX 76 MX	2004/09 –	2	6,396.00		
	DX 350	76/17 –04/12	2	N/A		31.07.2017
	DX 351	2000/09 –	2	2,450.00		
	DX 450	83/03 –16/12	2	4,000.00		31.12.2031
	DX 450 SCT	1983/03 –	2	7,175.00		
	DX 460	02/06 –17/12	2	1,865.00		31.12.2032
	DX 5	2017/06 –	2	2,650.00		
	DX A-40	94/03 –03/12	2	N/A	DX 460	31.07.2017
Gas-actuated (GX)	GX 100	10/09 –11/12	1	N/A	GX 3	31.12.2016
	GX 120	07/07 –17/12	2	4,582.00	GX 3	31.12.2024
	GX 120-ME	07/09 –17/12	2	4,582.00	GX 3	31.12.2024
	GX 3	2016/08 –	2	4,582.00		
Battery-actuated (BX)	BX 3	2016/04 –	2	4,086.00		

Hilti Tool Service – Cordless Lamp

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾	Successor Product	Repair Service Year	Repair service until (DD.MM.YYYY)
Cordless Lamp	SFL 14-A	2010/09 –	2	N/A		N/A	
	SFL 22-A	2010/09 –	2	N/A		N/A	
	SFL 36-A	2012/09 –	2	N/A		N/A	
	SL 2-A12		N/A	N/A		N/A	
	SL 2-A22		N/A	N/A		N/A	
	SL 2-A36		N/A	N/A		N/A	

Hilti Tool Service – Battery Charger

Product Group	Type	Production Period (YY/MM)	No Cost Period (Year)	Repair Cost Limit ¹⁾ (HKD)	Successor Product	Repair service until (DD.MM.YYYY)
Radio Charger	RC 4/36-DAB		2	1,345.00		

1) Valid until 31.12.2020. All prices subject to change.

"N/A" indicates non-reparable items which are not covered by Hilti Tool Services and warranty.

2) Unless otherwise specified, parts of direct fastening tools are kept normally for 10 years for repair services or Hilti will provide trade-in offer if parts are unavailable.

